

CLEAR FOCUS EasyCling™ Installation Instructions



Recommended tools:

- Soft-edged squeegee designed for wet or dry application
- Isopropyl alcohol (optional)
- Water or suitable application solution in a spray bottle
- Masking tape for creating 'hinges' and positioning graphic, if needed
- Clean cloth and lint-free towels
- Utility knife

Depending on the size of the graphic, EasyCling can be applied dry or wet using water or a suitable application fluid (e.g., a solution of water containing 2% mild liquid soap poured into a spray bottle). Wet application helps to prevent air bubbles from getting trapped between the film and the installation surface, and is recommended for graphics wider than about 18 inches.

During initial installation (wet or dry), EasyCling can be peeled easily from the mounting surface, repositioned and reapplied if needed.

Temperature of glass must be moderate — between approximately 40° F (5° C) and 90° F (32° C).

Preparation of Installation Surface

1. Wash the glass or other installation surface with mild soap and water. Rinse well with water. Do not use ammonia, Windex® or other solvent-based glass cleaner to clean the surface.
2. Moisten a clean cloth with isopropyl alcohol and wipe the surface to remove any residue. Dry with a lint-free towel.

Graphic Installation

1. Cut some strips of masking tape and have ready to attach to the top of the graphic to create a hinge, if needed.
2. For dry application of smaller graphics, position the graphic as desired and tape the top of it in place. Remove the liner and lower the graphic into position.

For wet application, lightly spray the installation surface with water or application fluid. Remove the liner from the graphic and position as desired.

3. Working from the center outward to the edges, squeegee the graphic using short, overlapping strokes to remove any trapped air bubbles, water or application fluid.
4. Wipe away any water or fluid and examine the graphic for any bubbles trapped under the surface. Use a squeegee to press and release any existing bubbles, and to squeegee the edges in place.
5. Remove the tape hinge from the graphic (if applicable).

It can take several days for any water to fully evaporate and the graphic to achieve clarity.

Questions? Call or email us with any product questions or for technical support.

CLEAR FOCUS Imaging, Inc. 60 Maxwell Court, Santa Rosa, CA 95401
Tel: 1-800-307-7990 ♦ 707-544-7990 ♦ Fax: 707-544-1886
Email: headoffice@clearfocus.com ♦ Web: www.clearfocus.com